



Logo Placements 6286 PW Trousers

Recommended logo placements

Heat seal & Embroidery

- 11 Rear side of left leg (calf), centered between the seams, start 5 above lowest point of leg.
- 16 Rear side of right leg (calf), centered between the seams, start 5 above lowest point of leg
- 28 Rear side of right leg, 1 cm from side seam, start 5 above lowest point of leg.
- 34 Rear side of left leg, 1 cm from side seam, start 5 above lowest point of leg.
- 100 Right leg, 2 cm above reflective, maximum size 120x100
- 101 Left leg, centered 2 cm above pocket seam, maximum size 100x100mm

Heat seal

- 18 Centered at right hip-pocket, maximum size 100x80
- 20 Left leg pocket maximum size 80x50 mm
- 30 Left thigh-pocket flap, maximum size 100x30 mm

Placement 11, 16, 28 and 34 maximum size,
for embroidery 250x80 mm and for heat seal 300x200 mm



How to keep
classification
ISO EN 11612

Labels, badges, retro-reflec-
tive materials, transfers, etc.,
which are applied to the
outermost surface of the
garment, with an area > 10
cm² shall be tested in ISO
15025, Procedure A.



Add

B after the placement and it will be below the (1B)

Y and it will be turned from bottom to top

Z after the placement and it will be turned from top to bottom



Left side of trouser